







# **ZW90** WYLDE PHASE

# DESCRIPTION

- Add shimmery velocity to lead licks, or add swoosh to chords
- Works well with bass, keyboards and even vocals
- Heard on Zakk's legendary blazing leads and solos
- Limited 2011 run

# **POWER**

The MXR Wylde Phase can be powered by one 9-volt battery (accessed by removing the bottom plate of the pedal), a Dunlop ECB003 AC adapter (ECB003E in Europe), or a Dunlop DCB10 DC Brick power supply.

#### DIRECTIONS

- Run a cable from your guitar to the Wylde Phase's Input jack and run another cable from the Wylde Phase's Output jack to your amplifier.
- Set the Wylde Phase's Speed control knob to the 12 o'clock position.

- Turn the effect on by depressing the footswitch.
- Rotating the Speed knob in a clockwise motion results in a faster phase effect, while rotating the knob counterclockwise results in a slower phase effect.

# **SPECIFICATIONS**

Input Impedance Output Impedance	1 MΩ 10 kΩ
Nominal Input	-20 dBV
Signal to Noise	> 96 dBA
Bypass	Hardwire
Current Draw	5 mA
Power Supply	DC 9 Volts

#### CONTROLS

- SPEED knob varies rate of phase sweep
- 2 FOOTSWITCH toggles effect on/bypass



# SAMPLE SETTINGS





DUNLOP MANUFACTURING, INC. P.O. BOX 846 BENICIA, CA 94510 U.S.A. TEL: 1-707-745-2722 FAX: 1-707-745-2658